

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2021

Submitted Date:

07/29/2021

Document Number:

699304166**FIELD INSPECTION FORM**Loc ID 336452 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243657	WELL	PR	07/01/2017	OW	123-11449	FREDERICK UNIT A 1	PR
243673	WELL	PR	03/17/1984	OW	123-11465	FREDERICK UNIT 'B' 1	PR
243972	WELL	PR	07/01/2017	OW	123-11764	FREDERICK UNIT C 1	PR
243973	WELL	PR	07/01/2017	OW	123-11765	FREDERICK UNIT D 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate x 4		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence x 4		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 4		
Comment:	Electrical transformers, breaker panel and meter.		
Corrective Action:		Date:	
Type: Pump Jack	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 4		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 243657	Type: WELL	API Number: 123-11449	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 11/04/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: appears to be plumbed to surface			
Corrective Action:		Date:	
Facility ID: 243673	Type: WELL	API Number: 123-11465	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 11/04/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: appears to be plumbed to surface			
Corrective Action:		Date:	
Facility ID: 243972	Type: WELL	API Number: 123-11764	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 11/04/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: appears to be plumbed to surface			
Corrective Action:		Date:	
Facility ID: 243973	Type: WELL	API Number: 123-11765	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHeadDate of Last Brhd Test: 11/04/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: appears to be plumbed to surface

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 7/29/2021 at approximately 1350 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up inspection to Doc # 699304154.</p> <p>Frederick Unit A Pad at Location #336452 in Weld County Colorado.</p> <p>While there, I observed a Multi well pad, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issue has been addressed: 608.e Mechanical condition: Leak around polish rod has been fixed and is no longer leaking.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	07/29/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304167	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5493424