

Inspection Photos  
Operator: Simcoe  
API: 067-07336  
Date: 7/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of erosion occurring and sediment discharge occurring within the southern project area. Stormwater BMPs need to be installed to stabilize erosion and prevent discharge into the Florida River.




Photo 3. View of Canada thistles observed on the southern fill slope. Approximately 150 individuals observed.



Photo 4. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses typical of irrigated grass field such as orchard grass, tall fescue, and perennial ryegrass.



Photo 6. View of the reference area comprised of irrigated grass field with irrigated grasses such as those described in Photo 5.