

Inspection Photos  
Operator: Simcoe  
API: 067-08773  
Date: 7/27/2021



Photo 1. View of the western project area from the western edge facing northeastward. Revegetation is progressing with western wheatgrass and smooth brome.





Photo 2. View of the northern portion of the interim reclamation area facing northward from the edge of the working area.





Photo 3. View of revegetation progressing along the pipeline running through the southern project area.





Photo 4. View of the reference area comprised of pinyon and juniper woodland with big sagebrush, mules ears, Indian ricegrass, and prickly pear.