

# Inspection Photos

API: 071-09475

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021

## Inspection Photos



**Photo 1.** There are multiple culverts along the road that are filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021



## Inspection Photos



**Photo 2.** Facing west along the main road at Lat/Long:37.1099,-104.94878. Erosion has occurred along the fill slope of the road. This area needs to be repaired and stabilized. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021



## Inspection Photos



**Photo 3.** This area of the road was where there was significant rutting. The road was graded but was not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021



## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021



## Inspection Photos



**Photo 5.** The soil pile at the location was disturbed and needs to be resloped and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021

## Inspection Photos



**Photo 6.** The fence around the pit is not maintained. This issue has been previously observed and needs adequately fenced and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 7/29/2021