

# Inspection Photos

API: 071-07944

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021

## Inspection Photos



**Photo 1.** Facing west toward the access road at the canyon bottom near AC 1-16. The road in the canyon bottom is not maintained or stabilized. Previous corrective action was not performed. Vehicle rutting and erosion was not repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021



## Inspection Photos



**Photo 2.** The road along the canyon bottom is not stabilized and maintained. Vehicle rutting and erosion has not been repaired. Arrow points to hard hat for scale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021



## Inspection Photos



**Photo 3.** The road along the canyon bottom is not stabilized and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021



## Inspection Photos



**Photo 4.** Stormwater accumulates on the road and is not diverted toward the culverts.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021



## Inspection Photos



**Photo 5.** Facing toward the access road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021



## Inspection Photos



**Photo 6.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 7/29/2021