

Inspection Photos

API: 071-08760

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021

Inspection Photos



Photo 1. Facing southwest along the main road at Lat/Long:37.12487,-104.95788. There is erosion occurring down the road. Stormwater needs to be diverted off the road to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021

Inspection Photos



Photo 2. Facing northeast along the main road at Lat/Long:37.119485,-104.95374. There is erosion occurring down the road. Stormwater needs to be diverted off the road to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021

Inspection Photos



Photo 3. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021

Inspection Photos



Photo 4. There is oil stained soils near the engine skid and oil inside the skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021

Inspection Photos



Photo 5. Traveling east along the main road near the location. This area has washed out and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08760 | Date: 7/29/2021