

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2021

Submitted Date:

08/02/2021

Document Number:

690102577

FIELD INSPECTION FORM

 Loc ID 335740 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 68710
 Name of Operator: PETERSON ENERGY OPERATING INC
 Address: 497 N DENVER AVENUE
 City: LOVELAND State: CO Zip: 80537
Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|----------------------------------|---------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Peterson, Andy | | andy.peterson@petersonenergy.com | |
| Dornbros, Ryan | | ryan@petersonenergyoperating.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|--------------------------|-------------|
| 203055 | WELL | SI | 04/01/2020 | OW | 001-08461 | AMOCO-UPRR 11-10 | TA |
| 203417 | WELL | SI | 04/01/2020 | GW | 001-08926 | AMOCO-UPRR 11-10X | TA |
| 446359 | TANK BATTERY | AC | 06/27/2016 | | - | AMOCO-UPRR-63S65W 11NWSE | EG |

General Comment:

COGCC Engineering Integrity Inspection; Flowline Removal Confirmation
Photos uploaded

Inspected Facilities

Facility ID: 203055 Type: WELL API Number: 001-08461 Status: SI Insp. Status: TA

Flowline

| #1 | Type: Well Site | of Lines |
|----|-----------------|----------|
|----|-----------------|----------|

Flowline Description

Flowline Type: Well Site Size: _____ Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Amoco UPRR 11 -10) is temporarily abandoned; on location wellhead flowline (approx 130' in length from wellhead to HHS) has been removed; Well (Amoco UPRR 11 -10X) is temporarily abandoned; wellhead flowline (approx 200' in length) is in the process of being removed. Facility serviced (2) wells (being decommissioned). On location dump and process flowlines are being removed. Tanks and equipment have been disconnected, isolated and moved/ removed. No Peterson Energy or contract personnel were on location at the time of this field inspection.

Corrective Action: _____

Date: _____

Facility ID: 203417 Type: WELL API Number: 001-08926 Status: SI Insp. Status: TA

Facility ID: 446359 Type: TANK API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 690102578 | Wellhead and signage | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495225 |
| 690102579 | Flowlines removed | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495226 |
| 690102580 | Wellhead; flowline removed trench backfilled | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495227 |