

Inspection Photos
Operator: Simcoe
API: 067-08758
Date: 7/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing within the project area with crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of cement washout and debris in the southwestern well pad and in the southeastern well pad (inset). Needs to be removed and properly disposed of.



Photo 5. View of the reference area comprised of sagebrush shrubland, gambel oak, and cottonwood riparian mosaic in a cobble floodplain with western wheatgrass and goldenaster.