

Inspection Photos
Operator: Simcoe
API: 067-09683
Date: 7/29/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the project area with crested wheatgrass, western wheatgrass, and James galleta.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of silt fence along the flowline right of way that is fallen, and no longer functioning.



Photo 5. View of the reference area comprised of open pinyon and juniper woodland with understory of sagebrush, James galleta, penstemon, squirreltail and western wheatgrass.