

Inspection Photos
Operator: Logos
API: 067-05521
Date: 7/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the project area with crested wheatgrass, western wheatgrass, and Arizona gumweed.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Willows and cottonwoods are becoming established here.



Photo 4. View of the reference area comprised of riparian and wetland vegetation with narrowleaf cottonwood, sandbar willows, cattails, smooth brome, and foxtail barley.



Photo 5. View of closed gate after leaving location.