

Inspection Photos
Operator: Simcoe
API: 067-07609
Date: 7/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing here with western wheatgrass, crested wheatgrass, and foxtail barley.



Photo 3. View of the southern project area from the southeastern corner facing southward. Vegetation here is grazed and sparse. Stormwater BMPs need to be installed and maintained until slope is stabilized.



Photo 4. View of small pieces of marker debris a wires scattered around the well pad. At least 10 pieces were observed.



Photo 5.

View of the reference area comprised of open pinyon and juniper woodland with understory of sagebrush, James galleta, penstemon, squirreltail and western wheatgrass.