

**Inspection Photos**  
**Location Name: UPRR 43 Pan AM G12**  
**Location ID: 318381**



**Photo 1 Weeds not maintained on access road.**



**Photo 2 Weeds not maintained on well site.**

**Inspection Photos**  
**Location Name: UPRR 43 Pan AM G12**  
**Location ID: 318381**



**Photo 3 loc pic**



**Photo 4 Weeds on location.**



**Inspection Photos**  
**Location Name: UPRR 43 Pan AM G12**  
**Location ID: 318381**



**Photo 5 Unused equipment: PU and associated equipment.  
Mechanical issue electric motor is not connected to power.**



**Photo 6 Electric power meter appears to have been  
removed.**