

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2021

Submitted Date:

08/03/2021

Document Number:

701101787**FIELD INSPECTION FORM**Loc ID 314987 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230038	WELL	PR	10/20/1976	GW	103-07697	FEDERAL 27-1	PR

**General Comment:****COGCC Routine Inspection Report Summary**

During this inspection the following compliance issues were observed:

- Nearest road not on sign. The battery sign is not at tank battery.
  - Weeds covering location.
  - Sediment moving on to location and riling from unstable slope behind tank and equipment. Sediment and riling moving off location. Access road ditches are filled with sediment. Access road is washing away is several areas.
- A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road is washing away is several areas. See storm water report.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No Api # on well sign.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Nearest road not on sign. The battery sign is not at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/04/2021

Emergency Contact Number:

Comment: 911  
800-791-7691

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds covering location.		
Corrective Action:	Comply with Rule 606	Date:	08/20/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	Open Top		,	

Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

**Flaring:**

Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	230038	Type:	WELL	API Number:	103-07697	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			Erosion of access road.
		Ditches	Fail			Ditches need maintained.
Ditches	Fail					
Compaction						

Comment: Sediment moving on to location and riling from unstable slope behind tank and equipment. Sediment and riling moving off location. Access road ditches are filled with sediment. Access road is washing away is several areas.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/20/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101798	Inspection 701101787 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497135">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497135</a>