

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 3 TB sign

Photo 4 Placards on Crude tank peeling, faded and need replaced

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 5 pump jack

Photo 6 electric panel

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 7 flow line manifold

Photo 8 Horizontal Heated separator

Inspection Photos
Location Name: Guildner #1
Location ID: 317889




Photo 9 Gas Meter Run

Photo 10 card in meter box indicates that calibration is not current

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 11 PW concrete vault, possible seepage

Photo 12 PW concrete vault, possible seepage

Inspection Photos
Location Name: Guildner #1
Location ID: 317889



Photo 13 Stained soil, slow leak around threads

Photo 14 Stained soil, slow leak around threads