

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0610-24-43 Pad,
Location ID: 324314



Photo #4654 from entrance to location.



Photo #4655 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0610-24-43 Pad,
Location ID: 324314



Photo #4656 No battery sign located at the tank battery.



Photo #4657 Insufficient velocity checks in ditch.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0610-24-43 Pad,
Location ID: 324314



Photo #4658 Gully erosion occurring in ditch.



Photo #4659 Sediment has been transported onto access road.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0610-24-43 Pad,

Location ID: 324314



Photo #4660 Inlet of culvert.



Photo #4661 Outlet of culvert.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0610-24-43 Pad,
Location ID: 324314



Photo #4662 Sediment has been transported down access road.