

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek /697-15-01

Location ID: 335921



Photo #4674 from entrance to location.



Photo #4675 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek /697-15-01

Location ID: 335921



**Photo #4676 No battery sign located at the tank battery.**



**Photo #4677 Access road lacks stabilization.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek /697-15-01

Location ID: 335921



**Photo #4678 Rill erosion occurring in ditch.**



**Photo #4679 Rill erosion occurring in ditch and access road.**



## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek /697-15-01

Location ID: 335921



**Photo #4680 Insufficient velocity checks.**



**Photo #4681 Insufficient velocity check.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources