

Location			
Lease Road:			
Type	Access		
comment:	well site and Tank battery are in a cattle pen.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate beginning to fade and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate starting to peel and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Faded and needs replaced		
Corrective Action:	Comply with Rule 605.g	Date:	10/29/2021
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barb wire, needs to be addressed due to livestock		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire, needs to be addressed due to livestock		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter Run has Ag panel		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	barb wire, needs to be addressed due to livestock	Date:	
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card in meter box indicates that calibration is not current		
Corrective Action:	Comply with Rule 430, Provide calibration records or calibrate meter as required. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).	Date:	10/29/2021
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 50 bbl					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		shares containment with crude tank			
Corrective Action:					Date:
Wells Served By Facilities Above					
API Number		AirsID			
123-07781		API Number		AirsID	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 239993 Type: WELL API Number: 123-07781 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/28/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 451454 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 7/29/2021 at approximately 1340 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at an KP Kauffman location: 1415 Corp Gas Unit B1 at API #05-123-07781 in Weld County Colorado. While there, I observed a well site and tank battery. PR at the time of inspection During this inspection the following possible compliance issues were observed: 605.g Signs General Condition: TB sign is not legible. CA date 10-29-2021, see photo 3. 430 Measurement of Gas: Meter not calibrated annually. CA date 10-29-2021. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	07/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402765137	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5493426
699304170	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5493425