

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2021

Submitted Date:

08/04/2021

Document Number:

699803503

**FIELD INSPECTION FORM**

Loc ID 334807 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210764	WELL	PR	09/17/1993	GW	045-06522	FEDERAL MV-12-3	PR
272043	WELL	PR	08/25/2004	GW	045-10007	FEDERAL GM 412-3	PR
272044	WELL	PR	08/22/2004	GW	045-10006	FEDERAL GM 312-3	PR
272045	WELL	PR	08/23/2004	GW	045-10005	FEDERAL GM 512-3	PR

**General Comment:**

COGCC Inspection Report Summary  
On Wednesday 8/4/21 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3SWNW, Location #334807 in Garfield County Colorado. While there, I observed normal production operations. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lfit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>210764</u>	Type:	<u>WELL</u>	API Number:	<u>045-06522</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>272043</u>	Type:	<u>WELL</u>	API Number:	<u>045-10007</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>272044</u>	Type:	<u>WELL</u>	API Number:	<u>045-10006</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>272045</u>	Type:	<u>WELL</u>	API Number:	<u>045-10005</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Compaction						
		Check Dams				
		Culverts				
Gravel						
		Ditches				
Berms						
Ditches						
Sediment Traps						
		Sediment Traps				
		Berms				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Refer to Storm water for comments.</span>	depaoloc	08/04/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803504	Photos for Insp. #699803503	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498590">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498590</a>