

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2021

Submitted Date:

08/05/2021

Document Number:

689806147

FIELD INSPECTION FORM

Loc ID 430051 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10525
Name of Operator: SANTA FE NATURAL RESOURCES INC
Address: 4833 FRONT STREET UNIT B 506
City: CASTLE ROCK State: CO Zip: 80104

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430052	WELL	SI	09/01/2016	OW	081-07747	Ridgeview 32-16-1	SI

General Comment:

Inspector on location to perform FLIR inspection. Purpose of FLIR to determine if fluid exists in tanks after leak reported from central tank labeled as "crude oil." Fluid observed with FLIR in tank labeled "produced water" no/low fluid observed in 2 tanks labeled "crude oil". Leak still ongoing at central tank. Fluid in tank battery berm.
Staining at separator base, no active leak observed. No fluid visible in separator using FLIR.

Inspected Facilities

Facility ID: 430052 Type: WELL API Number: 081-07747 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

