

Inspection Photos

API: 071-09004

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing south toward the location. The road continues thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 2. Facing south toward the lower portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 3. There was numerous noxious weeds observed at the location. Red arrow points to Canada thistle. Most of the weeds observed were wilted from recent weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 4. Facing northwest at the location. This area needs additional seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 5. Facing northwest toward the upper portion of the location.



Inspection Photos



Photo 6. North side of the location facing west. There is signs of erosion along the slope. This area needs additional seeding to help establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 7. Facing northeast toward the area shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021

Inspection Photos



Photo 8. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/4/2021