

Inspection Photos

API: 071-09549

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 1. Facing northwest along the preexisting road traveling to the location. There are pipe risers that remain that need to be removed as there are no active sites beyond this point.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 2. There is a second pipe riser that remains further along the road.



Inspection Photos



Photo 3. There is a culvert along the main road that has filled in with gravel and sediment which needs to be cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 4. Facing west along the preexisting road traveling to the location. There is a metal valve box that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 5. Facing west along the preexisting road traveling to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 6. Facing south along the preexisting road traveling to the location. The road is stabilized with vegetation along with other BMP's.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 7. Facing southeast toward the access road which was recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 8. Facing southeast along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 9. Facing southeast toward the location. There are noxious weeds shown at the red arrow which are wilted from recent weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 10. Facing southwest toward the location. The perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021

Inspection Photos



Photo 11. Facing southwest toward the upper portion of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/4/2021