

Inspection Photos

API: 071-09540

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/4/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the road traveling to the location. There A culvert further up is filled in with sediment causing erosion down the road in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021

Inspection Photos



Photo 2. Facing back to the southeast at the culvert filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021

Inspection Photos



Photo 3. Further up the road in the canyon is another culvert filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021

Inspection Photos



Photo 4. Facing southwest toward the access road. There are wilted noxious weeds from weed control observed along the road shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021

Inspection Photos



Photo 5. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021

Inspection Photos



Photo 6. Facing west toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09540 | Date: 8/4/2021