

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4711 from entrance to location.



Photo #4712 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4713 from entrance to location.




Photo #4714 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4715 Rill erosion occurring on cut slope.



Photo #4716 Ditch is filled with sediment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4717 Sediment is encroaching on production equipment.



Photo #4718 Ditch is no longer controlling run on to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4719 Sediment is encroaching on production equipment.



Photo #4720 Access road lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /34NWNW

Location ID: 335408



Photo #4721 Access road lacks stabilization.