

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2021

Submitted Date:

08/06/2021

Document Number:

699304204

FIELD INSPECTION FORM

Loc ID 332901 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	
McCartney, Ron		ron@mccartneyengineering.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263254	WELL	PA	01/25/2018	GW	123-20854	HEIN 15-25A	PA

General Comment:

Location

Lease Road:			
Type	Access		
comment:	well is in a gravel pit		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 263254 Type: WELL API Number: 123-20854 Status: PA Insp. Status: PA

Workover

Comment: Well is PA and is in a gravel pit the well is dead full of good cement, operations at the gravel pit have exposed the surface casing and needed it to be cut down. Operator had a welder cut 16 ft. 7 in. to ground level then had a cap and name plate welded on it.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 8/6/2021 at approximately 1140 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a McCartney Engineering location: Hein 15-25A at API #05-123-20854 in Weld County Colorado. While there, I observed an abandoned well, Well is PA and is in a gravel pit the well is dead full of good cement, operations at the gravel pit have exposed the surface casing and needed it to be cut down. Operator had a welder cut 16 ft. 7 in. to ground level then had a cap and name plate welded on it. During this inspection no compliance issues were observed: See attached photos. Location: dry, Weather: clear. I spoke with Jack McCartney with McCartney Engineering about the re-abandonment operations length of casing cut. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	08/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304205	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500524