

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Yellow steel tubing around electric equipment.

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Prime Mover	# 1			
Comment: Electric motor				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment: Electric equipment				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment: Inactive shut in gas pipeline				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment: Marked with Yellow steel tubing				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment: Plumbed to surface				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS			
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares containment with oil tank.				
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 269108 Type: WELL API Number: 001-06934 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 09/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -2 Fluid Type: _____

End Surf Csg Pressure: -2

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were hot, overcast, slight breeze.	medinaj	08/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503072	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500625