

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2021

Submitted Date:

08/06/2021

Document Number:

696104839**FIELD INSPECTION FORM**Loc ID 417752 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417751	WELL	PR	11/01/2019	OW	123-31738	Critter Creek 18-22H	SI

**General Comment:**

[This is a WELL / BATTERY inspection.](#)

[Well\(s\): 1: Shut-In | SI.](#)

[Battery: Inactive | Shut-down.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron mesh panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor. Controls crude oil tanks vapors. Pilots: OFF   Shut-down.		
Corrective Action:		Date:	

Type: Other	# 3		
Comment:	1: Electric power bank. 1: Line heater. Surrounded by protective shed. 1: Oil reycle pump. Surrounded by protective shed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	4 / 4: marked.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Not in operation.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Surrounded by earth berms, protective shed.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor drives pump jack. Shut-down.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber.		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	Not in use. Inactive.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration card indicates calibration within last year. Last calibration: 04/12/2021. Inactive. No production.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: <a href="#">Shares berms w/ crude oil tanks.</a>						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST		40.913863,-104.426900	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: <a href="#">Shares berms w/ produced H2O tank.</a>						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 417751 Type: WELL API Number: 123-31738 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: Appears shut-in. No gas sales indicated within 24 hours.  
ALL equipment appears shut-down.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/10/2021Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On THU 08/05/2021 at approximately 14:48 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: HIGHPOINT OPERATING CORPORATION  Location Name: Critter Creek /18-22H  Location ID: 417752  Well Name(s):  Critter Creek 18-22H.  API: 05-123-31738.  Location County: Weld County, Colorado  Weather: Mostly Sunny w/ Haze, damp/wet from prior storm.</p> <p>While there, I observed:  Well(s): 1: Shut-In   SI.  Battery: Inactive   Shut-down.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/06/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104840	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500689</a>