

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2021

Submitted Date:

08/09/2021

Document Number:

700703096

FIELD INSPECTION FORM

Loc ID 311850 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284185	WELL	PR	02/01/2021	GW	103-10738	FIGURE FOUR UNIT 8008D A16 498	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 8/6/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Figure Four A16, at Location # 311850 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area and BLM stipulations area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. During this inspection the following compliance issues were observed:

1. No battery signage.
2. Location shows signs of lack of stabilization/compaction
3. Weeds on location
4. One (1) dead man is not marked properly

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	No battery signage.			
Corrective Action:	Comply with rule 605.e			Date: 09/17/2021
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds on location			
Corrective Action:	remove or eliminate weeds			Date: 08/20/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Ancillary equipment	# 4			corrective date
Comment:	One (1) 500 gallon methanol tank in metal containment and Three (3) chemical tanks (2) at wells in plastic containment and (1) in tank containment			
Corrective Action:				Date:
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:	One (1) dead man is not marked properly		
Corrective Action:	mark or remove dead man		Date: 09/20/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	400 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 284185	Type: WELL	API Number: 103-10738	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
Compaction	Fail					

Comment: 1. Location shows signs of lack of stabilization/compaction

Corrective Action: Install or repair required BMPs

Date: 09/17/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703100	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5501086