

Inspection Photos

API: 071-06141

Operator: OGRIS OPERATING LLC

Inspection Date: 8/6/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 1. There has been maintenance performed on culverts along the road in the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 2. There is metal pipe markers laying on the ground near the culverts. The pipe needs to be removed or reinstalled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 3. It appears this culvert was cleaned out in the canyon and has since filled back in with debris. Ongoing maintenance is required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 4. Facing west at the switch back of the road where there was vehicle rutting. The road was graded however, the road was not stabilized and vehicle rutting may occur during wet winter condition.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 5. The erosion gully at the second switchback of the road was not repaired/stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 6. There is blue fiberglass pipe along area of the road that is broke apart and is trash. The pipe debris needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021

Inspection Photos



Photo 7. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 8/6/2021