

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2021

Submitted Date:

08/03/2021

Document Number:

688310988

FIELD INSPECTION FORM

Loc ID 320685 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections
Condill, JB	303-680-4725	jbrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204462	WELL	PR	08/01/2019	OW	005-06547	CHAMPLIN 126 AMOCO B 3	PR

General Comment:

[Routine Inspection](#)
[Document #402536658 04 \(--VENT_FLARE\) -00 Attachment count: 3 IN PROCESS 12/18/2020 12/18/2020](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: [Weeds sprayed.](#)

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: [electric](#)

Corrective Action:

Date:

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,

Comment:

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:	Inspector drove up to well and heard it venting. Contacted operator who called back and SI the field ASAP (i.e., that afternoon). Form 4 is in process-document # 402536658 04 (--VENT_FLARE) -00 Attachment count: 3 IN PROCESS 12/18/2020 12/18/2020		
Corrective Action:	Contact COGCC Engineer (DB).		Date: <u>08/17/2021</u>

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204462 Type: WELL API Number: 005-06547 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402769688	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497250
688311044	Renegade Champlin 126 Amoco B 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497239