



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Ag panel and hog fence		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 296367 Type: WELL API Number: 123-26724 Status: SI Insp. Status: SI

**Cement**

Cement Contractor

Contractor Name: Schlumberger Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 875-0 Cement Volume (sx): 265

Good Return During Job: YES Cement Type: G, AGM blend

Comment: Arrived on location at 0800 hrs. all personel on location having a safety meeting, Schlumberger NU and pressure test lines. Start mixing 265 sxs (57.1 bbl) 15.8 lbs Type G cement AGM blend and pump down hole for surface plug from 875ft. to 0 ft. with good cement returns (last 3 bbls) to circulation tank. Cement crew clean up RDMO. RIG crew WOC then RD and slide over to next well on pad.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 8/9/2021 at approximately 0800 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Oxy/Kerr McGee location:</p> <p align="right">Hauck 17-29 at API #05-123-26724 in Weld County Colorado.</p> <p>While there, I observed a Plugging operation, Form 42(PA) Doc # 402762049. Arrived on location at 0800 hrs. all personnel on location having a safety meeting, Schlumberger NU and pressure test lines. Start mixing 265 sxs (57.1 bbl) 15.8 lbs Type G cement AGM blend and pump down hole for surface plug from 875ft. to 0 ft. with good cement returns (last 3 bbls) to circulation tank. Cement crew clean up RDMO. RIG crew WOC then RD and slide over to next well on pad.</p> <p>During this inspection no compliance issues were observed:                      See attached photos.                      Location: dry, Weather: clear.</p> <p>I spoke with Seth Chappell Oxy Wellsite Supervisor about the current cement procedure, plug depth, number of cement sxs to be used.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	08/10/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304217	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5502824">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5502824</a>