

Inspection Photos

8/3/2021

Operator: GUNNISON ENERGY LLC #10515

Location ID: 453805

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 1: Photo of signage at Location entrance



Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 2: Photo taken from the fill slopes on the west end of the Location. Photo shows stormwater and erosion control measures to protect/stabilize the slopes of the Location, and to properly manage discharge remains missing or inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 3: Photo taken from the fill slopes on the west end of the Location. Photo shows stormwater and erosion control measures to protect/stabilize the slopes of the Location, and to properly manage discharge remains missing or inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 4: Photo taken from the cut slopes on the east end of the Location. Photo shows stormwater and erosion control measures to protect/stabilize the slopes of the Location remain missing or inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 5: Photo taken from the North end of the Location, facing south. Photo shows vegetation establishment is predominantly undesirable weedy plant species. Little to no desirable plant germination observed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 6: Photo taken from the south end of the Location, facing east. Photo shows vegetation establishment is predominantly undesirable weedy plant species. Little to no desirable plant germination observed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 7: Photo shows example of impacted stormwater issues observed on the Location due to various spills.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 8: Photo shows equipment remains improperly stored/placed within the stormwater diversion ditch on the eastern and southern perimeter of the pad.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



August 3, 2021
39.15630805N 107.47682189W



August 3, 2021
39.15719285N 107.47835795W

Photo 9: Photo taken from the southwest (left photo) and northwest (right photo) of the pad. Photo shows the stormwater outlets leading from the pad; erosion degradation remains evident at the outlets; BMPs has not been installed in accordance with good engineering practices, or maintained in proper functioning condition.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 10: Photo taken from the stormwater “ditch” leading from the Location. Photos show BMPs remain improperly constructed with vertical slopes and extracted soils left along channel remain unconsolidated and a pollutant source .

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



August 3, 2021

Photo 11: Photo shows stormwater and sediment discharge from the Location has filled the stormwater ditches and culvert.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 12: Photo taken from the sediment trap/pond west of the Location. Previous inspection documented that the inlets were inadequate. Photos show inlets remain inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 13: Photo shows example of improper materials management that has resulted in spills throughout the Location. This issues was documented in the previous inspection; proper materials management, covering and spill prevention on the Location remains insufficient.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



August 3, 2021
39.15751392N 107.47770945W



August 3, 2021
39.15736578N 107.4777142W

Photo 14: Photo shows example of stored materials onsite without proper covering to minimize contact of precipitation and stormwater runoff with materials, wastes, equipment, and activities with potential to result in discharges causing pollution of surface waters. This issue was documented in the previous inspection; proper materials management on the Location remains insufficient.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 15: Photo shows green barrels with unknown contents; photo shows example of barrels, and containers where labeling information remains missing. This issue was documented in the previous inspection.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 16: Photo shows example of barrels/tanks/containers observed stored on the Location without proper secondary containment. This issue was documented in the previous inspection; BMPs remain missing or insufficient to contain a spill.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 453805



Photo 18: Operator has placed 2 porta-johns on the Location. Porta-john on the south end of the Location has been properly secured. Photo shows porta-john on the north end of the Location that has not been properly secured in place

