

Inspection Photos

Operator: Black Resources
API: 083-06680
Date: 8/4/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of musk thistles within the project area. Approximately 150 flowering individuals observed.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within the reclamation areas with western wheatgrass, smooth brome, and yarrow observable.



Photo 4. View of areas on the well pad where little vegetation is present. These areas are likely not revegetating due to soil compaction or contamination issues.



Photo 5. View of area near the well pad entrance that is not reclaimed.



Photo 6. Another view of unreclaimed area at the entrance to the well pad.



Photo 7. View of soil mound in the northern project area, approximately 7ft high and 40ft long.



Photo 8. View of the reference area comprised of ponderosa pine and gambel oak woodland with understory of sandberg bluegrass, junegrass, yarrow, Oregon grape, and sugarbowl clematis.