

Inspection Photos

Operator: Black Resources
API: 083-06519
Date: 8/4/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here with western wheatgrass, smooth brome, rubber rabbitbrush, and yarrow.




Photo 3. View musk thistles observed within the project area. Approximately 100 flowering individuals observed.



Photo 4. View of the well head facing southward.



Photo 5. View of well sign, fencing, and well sock at the wellhead.



Photo 6. View of signage on the access road near the well pad entrance.



Photo 7. View of tent at gated access to location.



Photo 8. View of locked gate and entrance to access road.



Photo 9. View of the reference area comprised of ponderosa pine and gambel oak woodland with understory of sandberg bluegrass, junegrass, yarrow, Oregon grape, and sugarbowl clematis.