

Inspection Photos
Operator: Grynberg
API: 083-06378
Date: 8/4/2021



Photo 1. View of the access road from the access entrance facing north toward the well pad. Road fill, gravel, and culvert (inset) remain in place.



Photo 2. View of gravel and fill observed on the access road.



Photo 3. View of gravel on the well pad.



Photo 4. View of area on the former well pad where sparse vegetation remains. Soils may be compacted or contaminated here.



Photo 5. View of another portion of the project disturbance where revegetation is not progressing.



Photos 6-8. View of project wood and plastic liner debris observed partially buried within the project area, needs to be removed.



Photo 9. View of the reference area comprised of irrigated grass field with smooth brome, orchard grass, red fescue,