

Inspection Photos

8/3/2021

Operator: GUNNISON ENERGY LLC #10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



August 3, 2021
39.15646713N 107.47800007W

Photo 1: Photo shows sediment material improperly stored on the Location. Operator was observed removing/transporting sediment from the base of the cutslopes of the Trail Gulch Unit 1090 /30 Location, and placing/storing on the Federal 30-4 Location. No BMPs have been installed to prevent sediment transport from the stockpiled soils.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 2: Photo taken from the north end of the Location. Previous inspections required Operator to reclaim areas in accordance with 1003 rules. Photo shows areas have not been reclaimed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 3: Photo taken from the west of the Location. Photo shows various unused equipment and/or debris remains stored off of the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



August 3, 2021
39.15607241N 107.47770462W

Photo 4: Photo taken from the west end of the Location. Photo shows bucket containing unmown fluids; safety labeling identifying contents remain missing; buck has not been placed into secondary containment. These issues were identified in the previous inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 5: Photo shows barrel containing antifreeze/coolant stored on the Location without secondary containment. Photo also shows general Rule 606 good housekeeping issues observed on the location. Issues have been identified in previous inspections.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 6: Photo taken from the south end of the Location, facing east. Photo shows vegetation establishment is predominantly undesirable weedy plant species. Little to no desirable plant germination observed.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 7: Photo shows example of impacted stormwater issues observed on the Location due to various spills.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 8: Previous inspections observed that good-housekeeping practices were not being performed; various unused equipment, trash debris, and equipment not necessary for production on this Location observed stored on the site.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



August 3, 2021
39.15641679N 107.47773503W



August 3, 2021
39.15641951N 107.47772608W

Photo 9: Photo shows tubing on the Location that has not been stored in a workman-like manner.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 10: Photo taken from the access road west of the Location. Photo shows sediment discharge from the Location observed parallel to the access road.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 324464



Photo 11: Photo shows noxious weeds (bindweed) observed on the Location appears to have been sprayed with herbicide.