

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2021

Submitted Date:

08/05/2021

Document Number:

690102581

FIELD INSPECTION FORM

Loc ID 318529 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16910

Name of Operator: CHURCHILL ENERGY INC

Address: 2435 REED STREET

City: LAKEWOOD State: CO Zip: 80214

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kluksdahl, Gary		gary.kluksdahl@comcast.net	
Clark, Kellie		kmckmc2@aol.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Schultz, Scott		Scott.Schultz@coag.gov	
Love, Kimberley J.		kjlkjcar@aol.com	
Carroll, Kathy		kc2121@prodigy.net	
Crawford, John		ckccolorado@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241510	WELL	TA	09/01/2018	GW	123-09299	STROMBERGER UNIT 2-12	TA

General Comment:

COGCC Engineering Integrity Field Inspection conducted on 8/4/2021; Followup Inspection
NO Corrective Actions outlined on COGCC FIR Doc #690101849 submitted on 05/04/2020 have been completed by operator
Photos uploaded

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Corrective Action not completed by operator Incomplete signage at wellhead		
Corrective Action:	Update well sign to comply with Rule 210.b.	Date:	06/07/2020

Emergency Contact Number:

Comment:	Corrective Action not completed by operator NO ECN on location/ wellhead signage	
Corrective Action:	Update well sign to comply with Rule 210.b.	Date: 06/07/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:		corrective date
Type: Flow Line	#	
Comment:	Corrective Action not completed by operator; No flowline risers observed; on location flowlines appear to be abandoned in place and/ or removed. Work completed prior to conducting field inspection. Form 42 Notice of Pre-Abandonment of Flowlines has not been filed with COGCC.	
Corrective Action:	File COGCC Form 42 Notice of Pre-Abandonment of Flowlines with COGCC. 1105.d. Pre-abandonment notice requirements for flowline or crude oil transfer line for inspection. (1) For on-location flowlines, the operator must submit notice to the Director of the scheduled date for commencing abandonment with a Field Operations Notice, Form 42 Abandonment of Flowlines no less than 30 days before the operator will commence abandonment.	Date: 05/07/2020
Type: Gas Meter Run	# 1	
Comment:	Corrective Action not completed by operator; Out of service gas meter run on west side of location; unused equipment	
Corrective Action:	Remove unused equipment per rule 603.f	Date: 08/07/2020
Type: Other	#	
Comment:	Corrective Action not completed by operator; Broken master valve on wellhead. CA outlined on several COGCC FIR's; Most recently on FIR DOC #694400213 submitted on 09/17/2019.	
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date: 01/11/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		<100 BBLS	PBV FIBERGLASS		40.325310,-104.718020
Comment:	Corrective Action not completed by operator; The produced water fiberglass PBV has been removed (60 bbl)				
Corrective Action:	Operator shall submit an eForm 27, Site Investigation and Remediation Workplan, for the removal of the partially buried water vessel. The Workplan shall be submitted for prior COGCC approval and shall include a description of the proposed investigation and remediation activities in accordance with Rule 909.				
	Date: 06/07/2020				

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 241510 Type: WELL API Number: 123-09299 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Corrective Action not completed by operator;
Well is currently TA status; No flowline available. Production equipment has been removed; tank battery has been decommissioned and removed. Tank berms removed, location recontoured.

No MIT found in well file.

326. MECHANICAL INTEGRITY TESTING

c. Temporarily Abandoned Wells; All temporarily abandoned wells shall pass a mechanical integrity test.

(1) A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well.

Corrective Action: **Well must be either:**Date: 08/07/2020

1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or

2) Be properly plugged and abandoned.

3) A sundry requesting continued temporarily abandoned status should be submitted to Bob Koehler at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402771588	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498971
690102587	Incomplete signage at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498965
690102588	Broken master valve at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498966
690102589	View of location from wellhead; to SW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498967