

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2021

Submitted Date:

08/05/2021

Document Number:

693505379

FIELD INSPECTION FORM

 Loc ID 319921 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

6 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Young, Rob		rob.young@state.co.us	
,		dnr_cogccenforcement@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201895	WELL	PR	02/01/2021	OW	001-07299	GREEN 1	SI

General Comment:

Inspection due to passing corrective action dates on previous inspection Doc #688000543. All corrective actions and corrective action dates sill apply.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/18/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds on well site and production facility.		
Corrective Action:	Comply with rule 606	Date:	08/12/2021
Type	OTHER		
Comment:	Non E&P waste at pumping unit motor.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906	Date:	06/18/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter panel locked not able to access calibration card. Gas meter calibration record not legible or conspicuously displayed at meter.		
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		Date: 08/14/2021
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered motor skid. Motor leaking non E&P Waste onto the ground.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	06/18/2021
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Gauge hatch open or not sealed.				
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).				Date: 08/06/2021

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank.			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201895 Type: WELL API Number: 001-07299 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection flow line valves appear to be closed.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 11/10/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday August 5, 2021 at approximately 10:27, I, Inspector Randy Silver, conducted an follow up on-site inspection per doc# 688000543.</p> <p>Location: Green #1</p> <p>Operator: KP Kauffman</p> <p>API#:00107299</p> <p>County: Adams</p> <p>While there, I observed well site and production facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Non E&P waste: Rule 906 Corrective action date of 6-18-21 See photo 2</p> <p>Mechanical issue: Rule 608 e Corrective action date of 6-18-21 See photo 2</p> <p>WH sign: Rule 605 d corrective action date of 6-18-21 See photo 9</p> <p>Gauge hatch: Rule 608 a.(9) Corrective action date of 8-6-21 See photo</p> <p>Gas meter: Rule 430 d (2) Corrective action date of 8-14-21</p> <p>Weeds: Rule 606 Corrective action date of 8-12-21</p> <p>Weather conditions: Dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	08/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402771741	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5499086
693505380	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5499082