

# Inspection Photos

API: 071-08897

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021

## Inspection Photos



**Photo 1.** There is culvert at the beginning of the access road in the canyon that is filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021



## Inspection Photos



**Photo 2.** Facing south toward the access road. The access road has been regraded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021



## Inspection Photos



**Photo 3.** There is a sediment trap along the access road that is filled in with sediment. The sediment trap was not cleaned out. This could have been done by hand to avoid vegetation disturbance at the area shown at red arrow. Previous correction action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021



## Inspection Photos



**Photo 4.** Facing west toward the location fill slope. The valve box lid was left open and needs to be kept closed to prevent entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021

## Inspection Photos



**Photo 5.** There was a slight PW drip at the valve inside the box.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08897 | Date: 8/12/2021