

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	IGNITOR/COMBUSTOR		
Comment:	chainlink topped with barbless wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	chainlink topped with barbless wire		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	chainlink topped with barbless wire		
Corrective Action:			Date:

Equipment:

Type: Horizontal Heated Separator	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Oxy/Kerr McGee well is exposed at surface, KP Kauffman appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 7		
Comment:	automation, electric panel, meter box and transformers		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	card in meter house indicates current calibration		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Shares containment with crude tanks							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	OTHER	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)	315 bbl						
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Wells Served By Facilities Above				AirsID			
API Number		API Number		AirsID			
123-25653							
123-25449							
123-25431							
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 295052 Type: WELL API Number: 123-25653 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, Form 42(PR) Doc # 402692560 submitted on 5-18-2021

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/08/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 41 Fluid Type: Water

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/12/2021 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Oxy/Ker McGee location:</p> <p align="right">Stromquist 34-21 at API #05-123</p> <p>-25653 in Weld County Colorado, Locationis shared with a KP Kauffman well. This inspection is for the Stromquist 34-21 only. While there, I observed a wellsite and tank battery, SI at the time of inspection. During this inspection no compliance issues were observed: See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	08/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304237	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5505283