

Location			
Lease Road:			
Type	Access		
comment:	Weeds at Access Gate blocking Entrance to Location. See photos		
Corrective Action:	Comply with Rule 606	Date:	08/23/2021
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weed overgrowth on Location. See photos		
Corrective Action:	Comply with Rule 606	Date:	08/23/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		40.710003,-104.275281
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type	Field Flare				
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 417686 Type: WELL API Number: 123-31719 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Since 10.01.2019. MIT will be due on or before 10.01.2021 to maintain Shut-In Status.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: _____

End Surf Csg Pressure: 12

Comment: Annual Bradenhead Test is overdue.

Corrective Action: Comply with Rule 419.c Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Weeds blocking Entrance to Location. Weed overgrowth on Entire Location. Bradenhead Test is overdue; Comply with Rule 419.c. Well Shut-In since 10.01.2019. MIT due on or before 10.01.2021 to maintain Shut-In Status	petrie	08/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402773093	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500341
696303458	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5500331