

Inspection Photos
Operator: Advanced Wireless
API: 067-09317
Date: 8/6/2021



Photo 1. View of the northern project area from the northeastern corner facing westward.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing here, as described in July 2021 inspection.



Photo 3. View of Russian knapweeds remaining untreated within the interim reclamation area. Approximately 300 individuals observed.



Photo 4. View of eroding berms and water in tank containment. Sediment and water accumulation within containment is resulting in reduced and inadequate containment volume.



Photo 5. View of sediment discharge and rilling from unstabilized berms around tanks.