

Inspection Photos
Location Name: UPRR 43 Pan AM I #19
Location ID: 332976



Photo 1 P&A well site



Photo 2 unused equipment on P&A well site Electric pane and grading equipment.

Inspection Photos
Location Name: UPRR 43 Pan AM I #19
Location ID: 332976



Photo 3 KPK's equipment left on site.