

HILL RANCH 32-06 CH API# 05-071-08278 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201931



PHOTO 1: THE ORANGE FLAGGER TAPE WAS REMOVED. THIS WAS USED TO MARK THE END OF THE LEASE RUN FOR NEW HIRES. THERE WERE NO PIPELINE ISSUES, SOMEONE UNCOVERED THE VALVE CAN TO SEE WHAT WAS INSIDE AND FAILED TO REPLACE THE LID AS IT WAS TOO HEAVY. THE VALVE CAN COVER WAS PLACED BACK ON TOP OF THE VALVE CAN.



HILL RANCH 32-06 CH API# 05-071-08278 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201931



PHOTO 2: THE PIPELINE VALVE IS IN GOOD MECHANICAL CONDITION, THERE WERE NO ISSUES WITH THE PIPELINE. THE WATER IN THE VALVE BOX WAS RAIN WATER ONLY. THE ORANGE FLAGGER TAPE THAT WAS USED AT THIS INTERSECTION TO INDICATE THE END OF THAT RUN FOR NEW EMPLOYEE'S/CONTRACTOR'S HAS BEEN REMOVED.