

# Inspection Photos

API: 071-08576

Operator: RED RIVER RANCH HOLDINGS LLC


Inspection Date: 8/11/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Refer to the 2016 aerial image for issues observed during inspection. There was erosion shown at blue arrow which stormwater is causing erosion along the road side and at the water bars. BMP's need to be installed to prevent further erosion of these area. (e.g. rock rip/rap, rock check dams, sediment trap, ect.)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/11/2021

## Inspection Photos



**Photo 2.** Refer to the 2016 aerial image for issues observed during inspection. There was erosion shown at red arrow which concentrate stormwater off the road which then is redirected back onto the road. BMP's need to be installed to prevent further erosion of this area. (e.g. rock rip/rap, rock check dams, sediment trap, ect.)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/11/2021

## Inspection Photos



**Photo 3.** Facing east toward the location. The location is stabilized with native perennial vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/11/2021