

# Inspection Photos

API: 071-09344

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/11/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/11/2021

## Inspection Photos



**Photo 1.** Facing southeast along the pre-existing access road. There is erosion occurring down the road. Stormwater is not being diverted off the road and is concentrating flow down toward the location shown by red arrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/11/2021

## Inspection Photos



**Photo 2.** Facing south toward the access road at the location. The concentrated stormwater flow from previous photo has caused erosion of the access road. This area needs to be repaired and stabilized or reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/11/2021

## Inspection Photos



**Photo 3.** Facing northwest at the area shown in previous photo. There is an erosion channel which is caused by stormwater from the pre-existing access road shown in photo 1. This area will need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/11/2021

## Inspection Photos



**Photo 4.** Facing northeast toward the location. The location is stabilized with native perennial vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09344 | Date: 8/11/2021