

NEW ELK 35-01 API# 05-071-08469 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103936



PHOTO 1: THE PC COMPONENTS WERE REMOVED FROM THE LOCATION. THIS WELL WAS CONVERTED TO A JUMPING UNIT. ALL UNUSED EQUIPMENT HAS BEEN REMOVED FROM THE LOCATION.

NEW ELK 35-01 API# 05-071-08469 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103936



PHOTO 2: ALL VALVES, PIPES AND FITTINGS ARE SECURLY FASTENED. THE OIL ACCUMULATION IN THE RESERVIOR OF THE LIQUID RING SKID WAS REMOVED AND THE IMPACTED SOIL ON THE GROUND WAS CLEANED UP.

NEW ELK 35-01 API# 05-071-08469 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103936



PHOTO 3: THE OIL ACCUMULATION IN THE RESERVOIR OF THE LIQUID RING SKID WAS REMOVED AND THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.

NEW ELK 35-01 API# 05-071-08469 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: AUGUST 11, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103936



PHOTO 5: ALL VALVES, PIPES AND FITTINGS ARE SECURLY FASTENED. THE OIL ACCUMULATION IN THE RESERVIOR OF THE LIQUID RING SKID WAS REMOVED AND THE IMPACTED SOIL ON THE GROUND WAS CLEANED UP.