

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2021

Submitted Date:

08/16/2021

Document Number:

699803557

**FIELD INSPECTION FORM**

Loc ID 334342 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279080	WELL	PR	10/05/2010	GW	045-10994	HYRUP 2-46	PR
290317	WELL	PR	05/01/2012	GW	045-14072	HYRUP 2-23B	PR
290319	WELL	SI	10/01/2019	GW	045-14070	HYRUP 2-24A	SI
290321	WELL	PR	04/30/2010	GW	045-14068	HYRUP 2-33A	PR
290536	WELL	PR	03/01/2010	GW	045-14132	HYRUP 2-24C	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Friday 8/13/21 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at CAERUS PICEANCE LLC HYRUP-68S96W /2NESW, Location #334342 in Garfield County Colorado.  
Refer to document #699803413 inspection conducted on 7/16/21. All previous corrective action have been completed.  
While there, I observed normal production operations.  
This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separators		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		

Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 8			
Comment:	All meter runs have been calibrated in the last year.		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 8			
Comment:	All wells on plunger lift		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		

**Flaring:**

Type	
Comment:	
Corrective Action:	

<b>Inspected Facilities</b>				
Facility ID: <u>279080</u>	Type: <u>WELL</u>	API Number: <u>045-10994</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		
Facility ID: <u>290317</u>	Type: <u>WELL</u>	API Number: <u>045-14072</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		
Facility ID: <u>290319</u>	Type: <u>WELL</u>	API Number: <u>045-14070</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____				
Comment: <u>Last produced September 2019</u>				
Corrective Action:		Date:		
Facility ID: <u>290321</u>	Type: <u>WELL</u>	API Number: <u>045-14068</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		
Facility ID: <u>290536</u>	Type: <u>WELL</u>	API Number: <u>045-14132</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
Berms						
		Ditches				
Ditches						
Gravel						
		Sediment Traps				
		Culverts				
		Gravel				
		Berms				
Compaction						

Comment: Location appears to have been bladed with some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">fer to Storm water for comments.</a>	depaoloc	08/16/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803558	Photos for Insp. #699803557	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5507092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5507092</a>