

Inspection Photos
Operator: Hilcorp Energy
API: 067-08159
Date: 8/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern cut-slope from the southeastern corner facing northward. Revegetation is progressing similar to the reference area with smooth brome and western wheatgrass, as well as perennial weeds such as bindweed, largely in a grazed condition.




Photo 3. View of musk thistles within the project area. Approx. 25 individuals observed.



Photo 4. View of the western project area from the southwestern corner facing northward.



Photo 5. View of the reference area comprised of open grass field with smooth brome, western wheatgrass, and rubber rabbitbrush.