

Inspection Photos
Operator: Hilcorp Energy
API: 067-08247
Date: 8/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 1. View of erosional down-cutting and scouring (approx 2ft wide and 1ft deep) within the southern project area.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of black sage, James galleta, and green rabbitbrush.