

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-08747**  
**Date: 8/10/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of open grass field and ponderosa pine woodland mosaic with smooth brome gambel oak and yellow sweetclover.